

BMW Motorcycles of Oklahoma
417-C Hudiburg Circle
Oklahoma City, OK 73108
Phone: 405-948-4000 / 405-948-4001

Repair Order

Due: \$0.00

Doc Number: 45812
Service Writer: KELLEY LIPSCOMB
Date Printed: 01/06/2018
Date Promised: 01/06/2018

JOSEPH WEBB
108 SUMMIT RIDGE CT
NORMAN, OK 73071

Customer Information

Home Phone: 405-823-4410

 Fold Here

Summary

Unit	Job	Job Total
2016 BMW R1200GSA	FORK TUBE RECALL	WARRANTY

Job Subtotal:	\$0.00
Tax:	\$0.00
Total:	\$0.00
Less Deposits:	\$0.00
Total Due:	\$0.00

BMW MOTORCYCLES OF OKLAHOMA CITY and/or EuroTek OKC ("Dealership"), hereby expressly disclaims all warranties, either expressly implied, including any implied warranty of merchantability or fitness for particular purpose, and BMW MOTORCYCLES OF OKLAHOMA CITY/EuroTek OKC neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the parts or products listed. Dealer not responsible for unavailability of parts or delay in acquiring parts beyond dealer's control. All parts are new unless otherwise indicated. A Shop Supplies charge will be added for miscellaneous supplies used during the repairs of 15% of the total labor not to exceed \$15.50. All parts removed will be discarded unless otherwise instructed.

- ****NOTICE**** IF REPAIRS REQUIRE ORDERING PARTS, PARTS MUST BE 100% PREPAID IN ADVANCE DUE TO MANUFACTURERS' RETURN POLICIES.
- ****NOTICE**** Carburetor repairs cannot be guaranteed due to unpredictable fuel quality and improper storage. Customer is responsible for periodic check of accessory fasteners.
- ****NOTICE**** New tires are slick, due to manufactures' compounds. Please ride and stop with caution during the "break-in" period of new tires installed.
- ****NOTICE**** New chains may stretch rapidly. Please check adjustment often.
- ****NOTICE**** All vehicles left over 15 DAYS after completion of work will be assessed a storage fee of \$20.00 PER CALENDAR DAY.

ESTIMATES ARE VALID FOR 60 DAYS.

By signing below, I acknowledge that I was notified of and authorized the above services/repairs by the Dealership as itemized in this invoice, along with the necessary materials. Dealership employees may operate above vehicle for purposes of testing, inspection, delivery, or sublet work to be done at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs

thereto. Dealership is NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES IN VEHICLE IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND DEALERSHIP'S CONTROL.

X _____
Authorized Signature

Signature: _____

Detail

Unit 2016 BMW R1200GSA **Color:** **Keyboard:**
VIN/SerialWB10A1205GZ665706 **Plate:** **Odom/Hrs**27,085 **Out:**27,085

458121 - FORK TUBE RECALL

Description:INSPECT FOR TUBES REPLACE OR REPAIR
Resolution:FOUND NO GAP INSTALLED FORK TUBE BUSHINGS

DFC# 0000313000 RETROFITTING FORK TUBE WITH BUSHING
 FRC# 0060320 RETROFIT FORK TUBES WITH BUSHINGS
 FRU= 8
 FRC# 0060672 ADDITIONAL LABOR FOR PRESSING BUSHING
 FRU= 1
 FRC# 3199000 ADDITIONAL LABOR FOR PRESSING SECOND BUSHING
 FRU= 1
 TOTAL FRU= 10

Part #	Qty	Description	Price	Discount	Total
31427674776	2.00	O-RING	WARRANTY	WARRANTY	WARRANTY
31428396077	2.00	BUSH	WARRANTY	WARRANTY	WARRANTY
31427684743	2.00	HEX NUT	WARRANTY	WARRANTY	WARRANTY
Parts Subtotal					WARRANTY

Description	Technician	Hour	Total
REPLACE FORK TUBES AND INSTALL BUSHING	Brant Lynch	WARRANTY	WARRANTY
Labor Subtotal			WARRANTY
Job Subtotal			WARRANTY

All Jobs Subtotal: \$0.00
Tax: \$0.00
Total: \$0.00
Less Deposits: \$0.00
Total Due: \$0.00